

72445

ABANDONED/UNCONTROLLED HAZARDOUS WASTE SITE INVESTIGATIONS
PRELIMINARY ASSESSMENT REPORT

'3012' Grant Summary

Dugan & Helterbrand Company, Inc.
190 George Street
Marshfield, Missouri 65706

I. INVESTIGATOR: Charles L. Kroeger
Environmental Specialist
Waste Management Unit
Springfield Regional Office (SRO)
Missouri Department of Natural Resources

II. DATE INVESTIGATION INITIATED: July 15, 1985

DATE INVESTIGATION COMPLETED: September 19, 1985


III. BACKGROUND OF THE INVESTIGATION:

The Dugan and Helterbrand Company treats processed and raw photographic film and lithographic material for recovery of silver. The spent film chips had been going to the landfill without official DNR approval. Then in 1983 the company submitted application for and received special waste disposal approval to take the chips to the landfill.

In February 1985, sampling was performed at the Webster County Landfill in response to complaints by area residents. Samples were collected from streams of leachate and from a pile of chips recently taken there from Dugan & Helterbrand. The lab report indicated cyanide as high as 1.07 ppm in the leachate and 2,136 ppm in the chips.

Dugan & Helterbrand was immediately contacted and advised that they could no longer take chips to the landfill if the cyanide exceeded 250 ppm. A change in the hyperchlorite rinse of the plant reduced the cyanide to within the allowable range.

Dugan & Helterbrand is now in the process at converting to an enzyme process which would reduce the use of cyanide by 90%.



S00048640
SUPERFUND RECORDS

IV. IDENTITY OF PERSONS INTERVIEWED FOR THE REPORT:

Mr. Joe Helterbrand
Dugan & Helterbrand Co., Inc.
190 George Street
Marshfield, MO 65706

Association

President

(417) 468-3900

Mr. Bill Ralston
MO Department of Natural Resources
117 E. Dunklin
Jefferson City, MO 65102

Environmental Investigator

(314) 751-3241

V. BRIEF SUMMARY OF INFORMATION OBTAINED:

The company processed and disposed of an estimated 7,200 tons of film chips from 1979 to 1985. These film chips were treated with hyperchlorite solution prior to being taken to the Webster County Landfill; however the effectiveness of cyanide removal by the hyperchlorite apparently varied greatly resulting in some waste having total cyanide values of over 2,100 ppm. DNR has placed a limit of 250 ppm on waste to be disposed of in a sanitary landfill.

Sampling of private wells in the landfill area has not disclosed any adverse affects on the groundwater that can be attributed to the landfill or the Dugan & Helterbrand Company.

A spill at the plant in 1983 resulted in the death of several head of cattle owned by Mr. Helterbrand. The cattle reportedly are buried on site. An underground tank on the plant property was used to store spent cyanide solution. It is now empty and no longer used.

VI. DETAILED ACCOUNT OF THE INVESTIGATION:

During the investigation DNR officials spoke with Mr. Helterbrand concerning his operation and regarding the spill which occurred in 1983. Environmental Investigator Bill Ralston spoke with unidentified persons who were associated with the company or had knowledge of past events at the company. The facts obtained were presented to Mr. Helterbrand for his clarification.

Mr. Helterbrand related the process used to recover the silver from the film and explained that he had obtained the services of a consultant on destruction of the cyanide in the processed chips. DNR files confirmed this and contain a copy of the treatment process. Mr. Helterbrand indicated that he tested the processed chips with a colorimetric test to make certain the cyanide levels were low. The test apparently proved ineffective.

Mr. Helterbrand indicated that one of the process tanks leaked 50-100 gallons of process water that had the silver recovered from it but had not yet been treated to remove the cyanide. This water ran out of the building and pooled along the fence where cattle had access to it. Several head of cattle drank the water and died as a result of it. The cattle were buried on site, the pooled water was sucked up and returned to the tank and the spill area was treated with a sodium hypochlorite solution. The spill occurred from the west end of the east processing building. Dikes have since been constructed to prevent spillage from escaping out of the buildings.

Under directive by the DNR, Dugan & Helterbrand and the Department of Natural Resources tested each batch of processed chips prior to disposal at the landfill. Samples were collected and split primarily by DNR personnel and the chips were stored on site until both sets of results were reviewed and approval for disposal given. A summary of the test results is attached.

The plant is located at 190 George Street in Marshfield, Missouri. Latitude is 37° 19' 58", Longitude 092° 55' 20". The legal description is SE¼, SE¼, NW¼, Section 9, T30, R18. From the I-44 interchange at Marshfield travel south on Highway 38 for 0.7 mile to Washington Street (Old Highway 66). Travel 0.2 mile to George Street and travel south for 0.2 mile. The plant sets along the north side railroad tracks to the east of George Street.

The current property owner is Dugan and Helterbrand Co, Incorporated and the current operator is Mr. Joe Helterbrand, 116 George Street, Marshfield, Missouri 65706. Mr. Helterbrand also operated the business at the time of the burial of the cattle, spill at the tank and disposal in the Webster County Landfill.

The business consists of a series of metal buildings with concrete slab between the buildings. There is also a smelter on site for the silver.

The plant is set at the edge of an industrial area with residential and pastureland on two other sides. There is a shopping center within 1/4 mile of the site but little development other than industry in the drainage area below the plant.

The processed chips are temporarily stored on site in dumpsters on concrete pads until they can be hauled to the landfill. The tank in which spent cyanide solution was stored is now empty and no other disposal takes place on site. The cattle which died in 1983 are buried on the adjacent property.

The amount of processed material containing cyanide that is stored on site varies greatly. At times there may be as much as five dumpsters of chips on site but generally there will be none. The amount of cyanide contaminated soil and buried material is estimated to be 2 - 3 cubic yards.

According to the Division of Health's Health Assessment cyanides have been found to cause weakness, headaches, confusion, nausea, vomiting, eye and skin irritation and slow gasping respiration. Cyanide gas in sufficient concentrations can be lethal.

There are no known environmentally sensitive areas or water supplies in the immediate area. Any surface water flow from the site would flow south toward Lacey Creek however the plant site is relatively flat and there was apparently no runoff from any spills.

There are presently no known serious health problems attributed to the site. There were however, six head of cattle that died as a result of cyanide solution spill.

VII. CONCLUSIONS AND RECOMMENDATIONS:

It appears that with the change of processes and better control on the cyanide reduction process there should be no future hazardous wastes generated at the facility.

The two areas at which cyanide spills have occurred have reportedly been treated with sodium hypochlorite solutions to reduce the cyanide. It may be advisable however to sample the soils at the two spill areas and to sample the underground storage tank that is no longer in use.

SUBMITTED BY:

Charles L. Kroeger
Charles L. Kroeger
Environmental Specialist

Sept. 23, 1985
Date

VIII. ATTACHMENTS:

1. EPA Form 2070-12
2. Topographical map
3. County map
4. Plant layout
5. Results on Analysis of chips



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT
PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

29

II. SITE NAME AND LOCATION

| | | | | | |
|---|----------|---|-----------|----------------|----------------|
| 03 SITE NAME (Name of facility, street address, etc.) | | 04 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER | | | |
| Dugan & Helterbrand Co., Inc. | | 190 George Street | | | |
| 05 CITY | 04 STATE | 06 ZIP CODE | 08 COUNTY | 07 COUNTY CODE | 09 COND. DIST. |
| Marshfield | MO | 65706 | Webster | 225 | 7 |
| 08 COORDINATES LATITUDE | | LONGITUDE | | | |
| 37 19 58 | | 92 55 20 | | | |

10 DIRECTIONS TO SITE (Showing from nearest public road)

.2 mile southwest of Highway 38 on Old Highway 66 then .2 mile south on George Street in Marshfield, Missouri. Site is east of George Street.

III. RESPONSIBLE PARTIES

| | | | | | |
|--|----------|--|---------------------|--|--|
| 01 OWNER (if known) | | 02 STREET (Business, mailing, residential) | | | |
| Dugan & Helterbrand Co., Inc. | | 190 George Street | | | |
| 03 CITY | 04 STATE | 06 ZIP CODE | 08 TELEPHONE NUMBER | | |
| Marshfield | MO | 65706 | (417) 468-3900 | | |
| 07 OPERATOR (if known and different from owner) | | 08 STREET (Business, mailing, residential) | | | |
| Mr. Joe Helterbrand (Pres.) | | | | | |
| 09 CITY | 10 STATE | 11 ZIP CODE | 12 TELEPHONE NUMBER | | |
| Marshfield | MO | 65706 | () | | |
| 13 TYPE OF OWNERSHIP (Check one) | | | | | |
| <input checked="" type="checkbox"/> A. PRIVATE <input type="checkbox"/> B. FEDERAL: _____ <input type="checkbox"/> C. STATE <input type="checkbox"/> D. COUNTY <input type="checkbox"/> E. MUNICIPAL | | | | | |
| <input type="checkbox"/> F. OTHER: _____ <input type="checkbox"/> G. UNKNOWN | | | | | |

14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply)

☐ A. RCRA 3001 DATE RECEIVED: _____ ☐ B. UNCONTROLLED WASTE SITE (CERCLA 105) DATE RECEIVED: _____ ☒ C. NONE

IV. CHARACTERIZATION OF POTENTIAL HAZARD

| | | | | | |
|---|--|---|--|--|--|
| 01 ON SITE INSPECTION | | BY (Check all that apply) | | | |
| <input type="checkbox"/> YES DATE _____ <input type="checkbox"/> NO | | <input type="checkbox"/> A. EPA <input type="checkbox"/> B. EPA CONTRACTOR <input type="checkbox"/> C. STATE <input type="checkbox"/> D. OTHER CONTRACTOR | | | |
| | | <input type="checkbox"/> E. LOCAL HEALTH OFFICIAL <input type="checkbox"/> F. OTHER: _____ | | | |
| | | CONTRACTOR NAME(S): _____ | | | |
| 02 SITE STATUS (Check one) | | 03 YEARS OF OPERATION | | | |
| <input type="checkbox"/> A. ACTIVE <input type="checkbox"/> B. INACTIVE <input type="checkbox"/> C. UNKNOWN | | _____ BEGINNING YEAR ENDING YEAR <input type="checkbox"/> UNKNOWN | | | |

04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLEGED

05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION

V. PRIORITY ASSESSMENT

01 PRIORITY FOR INSPECTION (Check one. If high or medium is checked, complete Part 2 - Waste Information and Part 3 - Description of Hazardous Conditions and Impairment)

☐ A. HIGH (Inspection required promptly) ☐ B. MEDIUM (Inspection required) ☐ C. LOW (Inspect on time available basis) ☐ D. NONE (No further action needed, complete current disposition form)

VI. INFORMATION AVAILABLE FROM

| | | | | |
|--------------------------------------|--------------------------------|-----------------|---------------------|-------------------------|
| 01 CONTACT | 02 OF (Agency/Organization) | | 03 TELEPHONE NUMBER | |
| Joe Rowe | Hazardous Waste Management DNR | | (314) 751-3241 | |
| 04 PERSON RESPONSIBLE FOR ASSESSMENT | 06 AGENCY | 08 ORGANIZATION | 07 TELEPHONE NUMBER | 09 DATE |
| Charles L. Kroeger | DNR | SRO | (417) 883-4033 | _____ MONTH DAY YEAR |



☐ J. EXPLOSIVE
☐ K. REACTIVE
☐ L. INCOMPATIBLE
☐ M. NOT APPLICABLE

EPA FORM 2070-12 (7-81)



POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

29

II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)

01 ☐ J. DAMAGE TO FLORA
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ K. DAMAGE TO FAUNA
04 NARRATIVE DESCRIPTION (describe nature of species)

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ L. CONTAMINATION OF FOOD CHAIN
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ M. UNSTABLE CONTAINMENT OF WASTES
(Spills/runoffs/leaking drums)

03 POPULATION POTENTIALLY AFFECTED: _____

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

04 NARRATIVE DESCRIPTION

01 ☐ N. DAMAGE TO OFFSITE PROPERTY
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

01 ☐ P. ILLEGAL/UNAUTHORIZED DUMPING
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: _____)

☐ POTENTIAL

☐ ALLEGED

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS

III. TOTAL POPULATION POTENTIALLY AFFECTED: _____

IV. COMMENTS

V. SOURCES OF INFORMATION (Cite specific references, e.g., 2000 Res. Sample analysis, reports)

NTD



**POTENTIAL HAZARDOUS WASTE SITE
PRELIMINARY ASSESSMENT**

I. IDENTIFICATION

01 STATE 02 SITE NUMBER
29

II. DETAILED DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

A. HAZARDOUS CONDITIONS AND INCIDENTS

01 ☐ A. GROUNDWATER CONTAMINATION 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION

01 ☐ B. SURFACE WATER CONTAMINATION 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION

01 ☐ C. CONTAMINATION OF AIR 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION

01 ☐ D. FIRE/EXPLOSIVE CONDITIONS 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION


01 ☐ E. DIRECT CONTACT 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION

01 ☐ F. CONTAMINATION OF SOIL 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 AREA POTENTIALLY AFFECTED: _____ (Acres) 04 NARRATIVE DESCRIPTION


01 ☐ G. DRINKING WATER CONTAMINATION 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION

01 ☐ H. WORKER EXPOSURE/INJURY 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 WORKERS POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION


01 ☐ I. POPULATION EXPOSURE/INJURY 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
03 POPULATION POTENTIALLY AFFECTED: _____ 04 NARRATIVE DESCRIPTION



DETAIL OF PROPERTY





DETAIL OF BUILDINGS




East Process Building

@ Location of Sump Pumps
(2 Each Process Building)
Discharge to Empty Tank(s)

Spill Area



West Process Building and Office



Underground Storage Tank

Locations and Functions of Buildings Approximate

✓
JOHN ASHCROFT
Governor



Division of Energy
Division of Environmental Quality
Division of Geology and Land Survey
Division of Management Services
Division of Parks and
Historic Preservation

FREDERICK A. BRUNNER
Director

STATE OF MISSOURI
DEPARTMENT OF NATURAL RESOURCES

DIVISION OF ENVIRONMENTAL QUALITY

Springfield Regional Office
1155 East Cherokee Street
Springfield, MO 65807
417-883-4033

| Sample # | Date | Description | CaSi | (Actual) | EA, l |
|----------|---------|-----------------|-------|----------|-------|
| 85-3191 | 5-13-85 | processed chips | 51.5 | | 55.5 |
| 85-3192 | 5-13-85 | control #1 | 0.583 | 0.561 | .346 |
| 85-3164 | 5-28-85 | processed chips | 193 | | 208 |
| 85-3099 | 6-05-85 | processed chips | 160 | | 152 |
| 85-3181 | 5-07-85 | control #2 | 0.175 | .185 | .197 |
| 85-3187 | 6-10-85 | processed chips | 53 | | 63.5 |
| 85-3204 | 6-18-85 | processed chips | 192 | | 86.5 |
| 85-3205 | 5-07-85 | control #3 | 0.414 | .758 | .561 |
| 85-3209 | 6-27-85 | processed chips | 128 | | 131 |

JOHN ASHCROFT

FREDERICK A. BRUNNER



STATE OF MISSOURI
DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Springfield Regional Office

155 East Cherokee Street

Springfield, MO 65801

417-883-4033

12446
Division of Energy
Division of Environmental Quality
Division of Geology and Land Survey
Division of Management Services
Division of Parks and
Historic Preservation

Webster County

September 26, 1985

Mr. Joe Helterbrand
Dugan & Helterbrand Company, Inc.
190 George Street
Marshfield, MO 65706

Dear Mr. Helterbrand:

Please find enclosed the Hazardous Waste Compliance Inspection Report for the Dugan & Helterbrand Company at Marshfield in Webster County, Missouri. The report I believe is self explanatory.

The report indicates that Dugan & Helterbrand is in compliance with the hazardous waste law and regulations in that no hazardous wastes are being generated.

If you have any questions regarding the report, please contact Charles Kroeger of this office.

Sincerely,

SPRINGFIELD REGIONAL OFFICE

John R. Nixon, P.E.
Administrator

JRN/CLK/cg

Enclosure

cc: Webster County Court
bcc: Ms. Sandra Carroll, Waste Management Program

HAZARDOUS WASTE COMPLIANCE SECTION REPORT

DUGAN & HELTERBRAND COMPANY, INCORPORATED
190 George Street
Marshfield, Missouri 65706
(417) 468-3900
E.P.A. ID#: None
Mo. ID#: None
Contact: Mr. Joe Helterbrand, President

INTRODUCTION:

On September 17, 1985, Charles Kroeger, Missouri Department of Natural Resources, Springfield Regional Office, conducted a hazardous waste compliance inspection at the Dugan & Helterbrand Company at Marshfield in Webster County, Missouri.

Dugan & Helterbrand recovers silver from waste photographic and x-ray film. The film is hammer milled to nickle size pieces and placed in a rotating drum that immerses it in an enzyme solution. The enzyme solution removes the gel from the chips, thus, removing the silver. The liquid is then treated with a flocculant and the sludge containing the silver is shipped for smelting. Wastewater from the system discharges into the Marshfield municipal sewerage system and is regulated by the pretreatment ordinance.

For unexposed film chips and lithographic chips, Dugan and Helterbrand uses the cyanide extraction method. This is the method they used prior to installation of the enzyme process.

In the cyanide method, chips are placed in a tank and sodium cyanide is added to it. The reaction forms a silver cyanide complex that is pumped through a plating tank where the silver is extracted. The cyanide solution is then reused. The chips, after being processed with sodium cyanide, are rinsed with water which is then used as make up water for following batches. Sodium hyperchlorite is added to the processed chips to reduce remaining cyanide to cyanate which breaks down to form carbon dioxide and nitrogen. The waste chips are taken to the Webster County Sanitary Landfill.

UNSATISFACTORY FEATURES:

NONE

Hazardous Waste Compliance
Inspection Report
September 25, 1985
Page Two

COMMENTS:

The inspection disclosed that Dugan & Helterbrand Company, Incorporated is not a generator of hazardous waste in regulatable quantities. There has been a problem in their testing procedure and neutralization process in the past which allowed large quantities of chips high in cyanide to be disposed of in the landfill. However, the change in processes has apparently corrected this problem. At present, 90-95% of the film is processed by the enzyme process. The cyanide treatment is used only for lithographic film and unexposed film.

RECOMMENDATIONS:

NONE

APPROVED:

SUBMITTED BY:

John R. Nixon, P.E.
Administrator


Charles L. Kroeger
Environmental Specialist

Dugan & H. Howard Company, Inc
190 George Street
Warrensburg, Mo 65756
Representative: Mr. Joe Helterbrand
Title: President

Date: 9-17-85
Missouri I.D. #
EPA I.D. #
Phone Number 417 488-3900

this facility a TSD? N Transporter? N

Provide a brief description of the manufacturing process.

in this x-ray photography we pump material to machine press, then
in a drum that rotates through an engine solution. The solution removes
the gel from the plastic thus removing the silver. The liquid is then treated
with a flocculant and the flock, containing the silver, is sold to a silver
recovery facility. The waste water is generated by pretreatment and discharges
to the Marshfield municipal sewerage system.

| | Waste | Amount/month | Kilogram/month | I.D. # | Disposition |
|----|---|--------------|----------------|--------|-------------|
| 1. | <u>No Haz Waste</u> <u>Generated</u> | | | | |
| 2. | | | | | |
| 3. | | | | | |
| 4. | | | | | |
| 5. | | | | | |
| 6. | | | | | |
| | Total | | | | |

Subtract amount going to Resource Recovery or sewer
Amount subject to generator fee 0 (Fee is applicable if this value is over 10 kkg annually.
Fee based on generation from July 1 through June 30)
Is generator fee applicable to this facility? Yes No X (If yes, is it being paid? Yes No)
Is the head tax applicable to this facility? Yes No X (If yes, is it being paid? Yes No)
(Quarterly Annually)
Is the land disposal fee applicable to this facility? Yes No X (If yes, is it being paid? Yes No)
If the total amount of hazardous waste generated is less than 100 kg/month, is over 100 kg ever accumulated? Yes No
If the total amount of hazardous waste generated is less than 1000 kg/month, is over 1000 kg ever accumulated? Yes No
If 1000 kg is never accumulated, is hazardous waste disposed of within 1 year? Yes No
Has the generator determined if waste is hazardous? Yes No X it is not

A. MANIFESTS 10 CSR 25-8.010(4)

- 1. Generator's Missouri and EPA I.D. Numbers..... ☐
- 2. Serially increasing shipment number..... ☐
- 3. No. waste I.D. # correct..... ☐
- 4. Generator's name, address, phone number, EPA I.D. number... ☐
- 5. All transporters' names, addresses, phone numbers, and EPA I.D. numbers..... ☐
- 6. Hazardous waste management facility name, address, phone number, and EPA I.D. number..... ☐
- 7. Proper DOT shipping name and hazard class..... ☐
- 8. Quantity, container type, and number of units being shipped..... ☐
- 9. Emergency instructions and special handling procedures.... ☐
- 10. Proper certification..... ☐
- 11. Manifest properly signed and dated..... ☐

NA

- 13. Manifests returned within 30 days..... ☐
- 14. If not, exception generator report submitted within 48 days..... ☐
- 15. Completed manifests submitted to Department quarterly..... ☐
- B. CONTAINERIZATION AND LABELING 10 CSR 25-8.010(6)
- 16. Waste stored in proper DOT containers..... ☐
- 17. Containers labeled "Hazardous Waste" and labeled per proper DOT requirements during storage..... ☐
- C. STORAGE STANDARDS 10 CSR 25-7.050
- 18. Facility inspected and maintained..... ☐
- 19. Ignitable and reactive wastes properly handled..... ☐
- 20. Date of accumulation marked..... ☐
- 21. Storage less than 90 days (if applicable)..... ☐
- 22. Waste oil properly handled..... ☐

NA

In every month of less than 1000 lb. of waste
in any month of over 1000 lb. of waste

10 CSR 25-7.050 cross-referenced to
10 CSR 25-7.011(3)(F)

classroom or on-the-job training..... ☐

title, description, and name of person filling
position..... ☐

written record of the type and amount of training
given..... ☐

Documentation confirming that training has been given..... ☐

7. PREPAREDNESS AND PREVENTION 10 CSR 25-7.050(2)(A) cross-
referenced to 10 CSR 25-7.011(4)

7. Internal communication or alarm system..... ☐

8. Device in the hazardous waste operation area capable of
summoning emergency assistance..... ☐

9. Fire control, spill control, and decontamination equip-
ment available..... ☐

10. Adequate water supply for fire control equipment..... ☐

11. Adequate and proper safety equipment available..... ☐

12. Adequate aisle space..... ☐

13. Arrangements with local emergency agencies..... ☐

F. CONTINGENCY PLAN AND EMERGENCY PROCEDURES 10 CSR 25-7.050(2)(A)
cross-referenced to
10 CSR 25-7.011(5)

14. Contingency Plan..... ☐

15. Detailed description of procedures that personnel must
implement in response to fires, explosions, or release
of hazardous waste..... ☐

16. Describe formal arrangements with emergency agencies..... ☐

17. Names, addresses, and phone numbers (home & office) of
emergency coordinators..... ☐

18. Emergency equipment including its description and loca-
tion..... ☐

19. Evacuation plan if applicable..... ☐

Comment: _____

G. CONTAINER STORAGE 10 CSR 25-7.050(3)

40. Containers in good condition..... ☐

41. Containers storing incompatible wastes or products are
separated or protected from each other..... ☐

42. Containers kept closed in storage..... ☐

43. Containers stored within a waste confinement structure
(if applicable) that meets the criteria of 10 CSR 25-
7.050(3)(F)..... ☐

44. Containers of ignitable or reactive waste are stored
at least 50 feet from the property line..... ☐

Comment: _____

Inspector's Signature

Title

Office

Please mark boxes as shown

☒ In compliance

☐ In violation

HAZARDOUS WASTE STORAGE TANKS

Waste Contained

Volume of Tank

H. STORAGE TANKS 10 CSR 25-7.050(4)

45. Tanks in good condition..... ☐

46. Procedure for inspecting tanks..... ☐

47. Above ground tanks - adequate spill confinement
structures..... ☐

48. Underground tanks that cannot be entered have adequate
leak detection systems..... ☐

49. Leak detection procedure and schedule developed and
used..... ☐

50. Open tanks have _____ ft. freeboard..... ☐

51. Incompatible wastes in tanks safely and properly
stored..... ☐

52. Volatiles are not placed in open tanks..... ☐

53. Ignitable or reactive wastes in tanks safely and
properly stored..... ☐

54. Ignitable or reactive wastes in covered tanks stored
in accordance with NFPA's buffer zone requirements..... ☐

55. Controls to prevent overfilling..... ☐

56. Daily inspection of overfilling control equipment..... ☐

57. Daily inspection of freeboard in uncovered tanks..... ☐

Comments:

HDH

[illegible]

